PO Box 518
620 Applegate St.
Philomath, OR 97370

WET●Labs

(541) 929-5650
Fax (541) 929-5277
www.wetlabs.com

ECO CDOM Fluorometer Characterization Sheet

Date: 2/19/2019   S/N: BBFL2IRB-5498

CDOM concentration expressed in ppb can be derived using the equation:

CDOM (ppb) = Scale Factor * (Output - Dark Counts)

	Digital
Dark Counts	49 counts
Scale Factor (SF)	0.0912 ppb/count
Maximum Output	4130 counts
Resolution	1.0 counts
Ambient temperature during characterization	23.3 °C

Dark Counts: Signal output of the meter in clean water with black tape over detector.

SF: Determined using the following equation: $SF = x \div (\text{output - dark counts})$, where x is the concentration of the solution used during instrument characterization. SF is used to derive instrument output concentration from the raw signal output of the fluorometer.

Maximum Output: Maximum signal output the fluorometer is capable of.

Resolution: Standard deviation of 1 minute of collected data.