



SEA-BIRD
SCIENTIFIC

SBE41-CP ALACE

Instrument Configuration

Instrument Serial Number: 41-12941
Instrument Firmware Version: 7.2.5
Zero Conductivity Frequency: 2653.74
Communications Format: RS232
Communications Settings: 9600 baud, 8 Data Bits, No Parity

Installed Devices/Sensors

<i>Data Format</i>	<i>Measurement</i>	<i>Sensor Type</i>	<i>Serial Number</i>	<i>Rating</i>
Count	Temperature	Internal	N/A	N/A
Frequency	Conductivity	Internal	N/A	N/A
Count	Pressure	Druck	11515731	2000m(2000 dBar)



Sea-Bird Scientific
13431 NE 20th Street
Bellevue, WA 98005
USA

+1 425-643-9866
seabird@seabird.com
www.seabird.com

SENSOR SERIAL NUMBER: 12941
CALIBRATION DATE: 06-Jun-20

SBE 41 TEMPERATURE CALIBRATION DATA
ITS-90 TEMPERATURE SCALE

COEFFICIENTS:


a0 = -8.607614e-004
a1 = 2.951725e-004
a2 = -3.803435e-006
a3 = 1.533566e-007

BATH TEMP (° C)	INSTRUMENT OUTPUT (counts)	INST TEMP (° C)	RESIDUAL (° C)
0.9999	13906828.0	0.9999	0.0000
4.5000	11892930.8	4.5000	-0.0000
15.0000	7584120.4	15.0000	0.0000
18.5000	6568326.7	18.5000	0.0000
23.9941	5272108.3	23.9941	-0.0000
29.0000	4341266.3	29.0000	-0.0000
32.5000	3802395.7	32.5000	0.0000

n = Instrument Output (counts)

Temperature ITS-90 (°C) = $1 / \{a_0 + a_1[\ln(n)] + a_2[\ln^2(n)] + a_3[\ln^3(n)]\} - 273.15$

Residual (°C) = instrument temperature - bath temperature





Sea-Bird Scientific
13431 NE 20th Street
Bellevue, WA 98005
USA

+1 425-643-9866
seabird@seabird.com
www.seabird.com

SENSOR SERIAL NUMBER: 12941
CALIBRATION DATE: 06-Jun-20

SBE 41 CONDUCTIVITY CALIBRATION DATA
PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

g = -1.031325e+000
h = 1.465031e-001
i = -1.038097e-004
j = 3.089072e-005

CPcor = -9.5700e-008
CTcor = 3.2500e-006
WBOTC = 4.7098e-007


BATH TEMP (° C)	BATH SAL (PSU)	BATH COND (S/m)	INSTRUMENT OUTPUT (Hz)	INSTRUMENT COND (S/m)	RESIDUAL (S/m)
22.0000	0.0000	0.00000	2653.74	0.00000	0.00000
0.9999	34.8502	2.97858	5226.34	2.97857	-0.00001
4.5000	34.8322	3.28608	5422.24	3.28608	0.00000
15.0000	34.7957	4.26935	6005.15	4.26936	0.00000
18.5000	34.7889	4.61513	6196.84	4.61513	0.00000
23.9941	34.7819	5.17346	6494.14	5.17346	-0.00000
29.0000	34.7780	5.69675	6760.61	5.69674	-0.00001
32.5000	34.7738	6.06942	6943.98	6.06942	0.00001

$f = \text{Instrument Output(Hz)} * \sqrt{1.0 + \text{WBOTC} * t} / 1000.0$

t = temperature (°C); p = pressure (decibars); $\delta = \text{CTcor}$; $\epsilon = \text{CPcor}$;

$\text{Conductivity (S/m)} = (g + h * f^2 + i * f^3 + j * f^4) / (1 + \delta * t + \epsilon * p)$

Residual (Siemens/meter) = instrument conductivity - bath conductivity





Sea-Bird Scientific
13431 NE 20th Street
Bellevue, WA 98005
USA

+1 425-643-9866
seabird@seabird.com
www.seabird.com

SENSOR SERIAL NUMBER: 12941
CALIBRATION DATE: 02-Jun-20

SBE 41 PRESSURE CALIBRATION DATA
2900 psia S/N 11515731

COEFFICIENTS:

PA0 =	2.158104e-001	PTCA0 =	-6.036934e+003
PA1 =	3.930919e-004	PTCA1 =	3.331621e+001
PA2 =	-2.729786e-013	PTCA2 =	-4.145572e-001
PTHA0 =	3.443734e+002	PTCB0 =	3.129713e+005
PTHA1 =	-6.352433e-005	PTCB1 =	-1.952185e+000
PTHA2 =	-1.551480e-012	PTCB2 =	6.315748e-002

PRESSURE SPAN CALIBRATION

THERMAL CORRECTION

PRESSURE (PSIA)	INSTRUMENT OUTPUT (counts)	THERMISTOR OUTPUT (counts)	COMPUTED PRESSURE (PSIA)	RESIDUAL (%FSR)	TEMP (°C)	THERMISTOR OUTPUT (counts)	INSTRUMENT OUTPUT (counts)
14.59	31313.3	4550984.4	14.68	0.00	32.50	4430186.40	32204.70
590.70	1498408.6	4549176.4	590.79	0.00	29.00	4475411.00	32285.54
1166.66	2968225.8	4548286.0	1166.79	0.00	23.99	4539971.00	32263.74
1742.65	4441332.5	4547447.2	1742.89	0.01	18.50	4610685.80	32076.61
2318.69	5917006.7	4546622.2	2318.81	0.00	15.00	4655690.20	31958.13
2894.62	7395274.1	4545721.6	2894.54	-0.00	4.50	4789867.40	31773.15
2318.52	5916275.7	4545845.6	2318.52	0.00	1.00	4834577.20	31664.29
1742.93	4440963.2	4546050.6	1742.74	-0.01	TEMPERATURE (°C) SPAN		
1166.74	2967613.7	4546282.4	1166.54	-0.01			
590.56	1497405.6	4546538.2	590.39	-0.01			
14.58	30979.9	4546495.6	14.55	-0.00			
					1.28	312968.93	
					20.35	312957.75	
					34.23	312978.50	

y = thermistor output (counts)

t = PTHA0 + PTHA1 * y + PTHA2 * y²

x = instrument output - PTCA0 - PTCA1 * t - PTCA2 * t²

n = x * PTCB0 / (PTCB0 + PTCB1 * t + PTCB2 * t²)

pressure (PSIA) = PA0 + PA1 * n + PA2 * n²

Residual (%FSR) = (computed pressure - true pressure) * 100 / Full Scale Range

Date, Offset (%FSR)

● 02-Jun-20 0.00

